i i		50X1	
•		コリネー	1
			4
Declassified in Part - Sanitiz	ed Copy Approved for Release 2014/05/1	14 : CIA-RDP78-03153A001800030012-9	
	- ASH #	<i>[</i>	

## 2 March 1954

MEMORANDUM FOR	THE RECORD	,	
SUBJECT:	Meeting with	Representatives	50X1
1. Time a	and Place of Meeting:	on to repruary 1954.	50X1 50X1
2. Attend	lance:		50X1
on Contract RD	-50, Project P-60A, Ta		50X1
of	300 sq. ft. of XRX-55	filter material and one	50X1
was also a que a person to as No answer was	leared. No answer was stion as to when the A sist in setting up all	wanted to know immediately available. There gency was going to send over lowable overhead books, etc. ioned want polarity of the unswer available.	50X1
		rning off mantle with a match, and Gallanger glass filter.	
		ckaging requirements the drop read four feet instead of ten	
		they might want to make minor	50X1
modifications which would speed production and facilitate field maintenance. It was suggested that prepare a list of these for approval or disapproval by Project Officer. This is to be			50X1
	s possible at the conv		50X1
Only minor det	appears ve	ery nearly ready for production. ared up.	50X <sup>2</sup>
		5. Actions/	

Declassified in Part - Sanitized Copy Approved for Release 2014/05/14: CIA-RDP78-03153A001800030012-9

5. Actions:	
	50X1
(a) Study production problem and come up with list of proposed modifications.	•
(b) Inform Project Officer as to when consideration will be convenient.	
APD:	
(a) Check on clearances with Security.	50X1
(b) Check on polarizing effect of filter.	
(c) Check on contracts man to help set up T&A for	50X1
(d) Check burning off mantle with match.	
(e) Use of ceramic mantles.	•
	50X1
TSS/APD ·	• .

Distribution:

1 - P-60A

1 - RTW 1 - Chrono

RTW/br